#	Oakland Facility Assessment Checklist Instructions
1	City of Oakland tab: Existing Documentation section items are requested to be provided to Consultant before site assessment.
2	City of Oakland tab: Facilities and User Questions section is to be completed by Public Works and building user groups.
3	Summary tab is meant to be a quick review of major building systems. See Systems tab for more detail.
4	Accessibility tab: initial accessibility review items provided as indicators for items requiring further investigation. Accessibility review is not CASP level review or inspection.
5	Systems tab: provide unique 3-digit number in first column labeled ### for identification. Numbers to be added at end of assessment process.
	Systems tab: delete unused rows in spreadsheet and add new rows as needed for building components.
7	Systems tab: maintain 1 letter + 4-digit numbering system when removing and adding new rows. If items in group exceed ten items group can expand to the next tenth grouping. Adjust overall numbering scheme as needed.
8	See additional associated reviews and reports for structural and specific building types provided under separate cover.
9	Cost columns highlighted red are reserved for future use.

			YES/		
#	SYSTEM	ITEM	NO	DESCRIPTION	COMMENT
1		Existing Documentation			
2		Existing drawings	Yes	Uploaded to consultant FTP site	
3		Major renovations			
4		Geotechnical reports		None available	
5		Energy audits and/or utility records		See folder	
6		Hazardous material reports		See Appendix	
7		Other reports (assessments)			
		Facilities and User Questions			
		Are there any major building components frequently out of order or			
		that require consistent maintenance? i.e. elevator			
11					
12		Are there any roof leaks?			
13		Are there any major plumbing backup issues?			
14		Any plumbing fixture leaks or issues?			
		Does the mechanical system need frequent adjustment?			
15					
16		Are any electrical breakers tripped consistently?			
		Are utility costs abnormally high for this building?			
17		, , , , ,			
		Are there complaints from building users about thermal comfort?			
18					
		Any reported issues with or concerns about indoor air quality?			
19					
20		Are there any other notable issues with the building?			

###	SYSTEM	ITEM	NUMBER	DESCRIPTION	COMMENT
	Т	Building Summary			
	T10	Overall			
100	T1010	Year constructed		Circa 1960's but no known date; Seismic Retrofit and Other Improvements 1995	
101	T1011	Number of stories		One	
102	T1012	Building setting		Suburban	
103	T1013	Approximate building height		16-feet (not including tower)	
104	T1014	Estimated building area		~5500 SF	
105	T1015	Occupancy Group and Use		Fire Station: R3 (residential) and S2 (Storage)	
106	T1016	Superstructure system		Wood-framed with steel moment frame retrofit	
107	T1017	Roof type		Asphalt shingle steep-slope and asphalt roll low-slope	
108	T1018	Approximate number of parking spaces (if applicable)		Large parking lot, no striping	
109	T1019	Elevator or lift		None, one story	
110	T1020	Number of stairs		Exterior only	
111	T1021	Number of exits		4	
	T1021.01	Exit configuration		Dormitory 11,12,13, All Gender 7 and Toilet 9 exit thru App Bay	Non conforming
112	T1022	Exit signage		none	
113	T1023	Accessory structures on site		one shed, used for Fitness Facility	
	T1024	Openings between sleeping rooms and App Bay		Officers Room 1 has door to App Bay with transom; no openings should be provided directly between motor vehic related occ and room for sleeping	Non conforming
	T0125	Occupancy Separations R3 (dwelling rooms)		None - doors not rated; 1 hr required	Non conforming
	T0126	Occupancy Separations R3-S2 (dwelling rooms/app bay		None- doors not rated ; 2 hr required	Non conforming

	T50	Systems General		
114	T5010	Total number of toilet fixtures	4	
115	T5011	Total number of addtl. plumbing fixtures incl. showers	(1) urinal, (4) shower stall, (5) lavs, (1) mop sink, (1) kitchen sink	
116	T5012	Fire sprinkler system	None	Non conforming
117	T5013	Mechanical system	Central Furnace mounted high in app bay provides heating to both sides of the FH. One year old. Great condition	
117	T5013	Electrical system: ECAP readiness	150A 120/240 single phase service. Service installed in 1997. Good condition	

###	SYSTEM	ITEM	LOCATION	DESCRIPTION	COMMENT	COST
	М	Accessibility				
	M10	Exterior				
200	M1010	Exterior path of travel to entry		No POT from ROW or parking lot	Non-conforming	
201	M1011	Interior path of travel from entry to all required spaces		See issues listed under section M20 Interior General	Non-conforming	
202	M1012	Accessible parking space, van, and/or drop-off zone		No parking lot striping or accessible parking spaces	Non-conforming	
203	M1013	Accessible parking signage		No parking signage	Non-conforming	
204	M1014	Curb ramps		na		
205	M1015	Entrance	Front door entrance	No clear and level landing or signage at front door; threshold is not flush and is non-compliant	Non-conforming	
	M20	Interior General				
210	M2010	Elevator and lifts; accessible controls		None required; one story building		
211	M2011	High-low drinking fountain w/CFA		None provided		
212	M2012	Visual and audible alarms			Check with MEP	
213	M2013	Tactile signage		None at building interior nor exterior		
214	M2014	Door hardware	Doors 1,3,4,7,8, 13, 14, 15, 16, 17, 18	No lever hardware (existing knobs)	Non-conforming	
	M2014.01	Closet hardware	Doors 2A, 2B	No lever hardware (existing knobs)	Non-conforming	
	M2014.02	Door Hardware - 10" high smooth surface from floor on bottom of door at push side	Door 7, 14	Door has kick stop on push side, which obstructs smooth surface	Non-conforming	
	M2015.01	Pull side latch clearance	Door 12	Door has <18" pull side latch clearance, located in alcove	Non-conforming	
	M2015.02	Pull and push side latch clearance	Door 13	Door has <18" pull side latch clearance and <12" push side latch clearance, located in alcove	Non-conforming	
	M2015.03	Door width	Door 15,16,17	Dorm doors are 32"; 36" required.	Non-conforming	
-	M2016	Flush transitions and door thresholds	Door 19	Threshold >.5" with .25" max vertical rise	Non-conforming	
217	M2017	Ramps (measure w/ level)		No ramps in building		
	M2019	Accessories mounting heights	Kitchen 3	Soap and paper towel dispenser at kitchen mounted higher than 40" to operable parts	Non-conforming	
	M30	Restrooms				
220	M3010.01	Toilet Room 1A (officers') clearances	Toilet Rm 1A (officers')	Required clearances not provided at door 3, toilet or lav, nor accessories (very small space). (see floor plan attached)	Non-conforming	
221	M3010.02	Toilet Room and Shower 9 clearances	Toilet Rm 9	Clearances not provided include: Urinal and its stall; non complying Toilet stalls too small; non complying (3) shower stalls too small; non-complying Paper towel dispenser mtd >40" AFF (40" max req)	Non-conforming	

	M3010.03	All Gender Toilet and Shower 7 clearances Special Accessible Conditions	All Gender 7	Clearances not provided include: 28.5" clear under sink at skirt; 29" required Sink knee clearance <8" required to bowl Toilet stall is 48" wide (60" required) Toilet stall <48" clear in front of toilet (48" required) Stall door not self closing (self closing required) Shower stall 42x54 w/bench opp controls non complying Soap and paper towel mtd >40" AFF (40" max req)	Non-conforming	
230	M5010	Service counter		none		
		Kitchen counter	Kitchen 3	Quartz counter in good shape, but counter too high ; >36"	Non-conforming	
		Kitchen worksurface next to oven	Kitchen 7	No work surface provided adjacent to bottom hinged oven door (11B-804.6.5.2)	Non-conforming	
		Kitchen worksurface with knee space	Kitchen 7	None provided at fixed counter	Non-conforming	
		Electrical Switches	Rms 2	Located too high; >48"; approximately (10)	Non-conforming	
		Electrical Outlets Mounting Heights	all	Outlets - over counter too high >48"; Most low outlets in building located too close to floor <15" AFF Approximately (15)	Non-conforming	
233	M5013	Benches		NA/no locker room		
234	M5014	Washer clear space	Laundry 6	no clear floor space provided	Non-conforming	

# SYSTEM	ITEM	LOCATION	DESCRIPTION	MAINTENANCE	QTY	UNIT	PRIORITY	COST
Α	Substructure							
A10	Foundations							
A1010	Standard Foundations							
A1011	Wall Foundations							
			Continuous shallow footings (sizes unknown) under bearing walls, 4 foot					
			square pad footings under moment frame					
A40	Slab On Grade							
A4010	Standard Slabs-on-Grade							
A4011	Slab On Grade		6" concrete slab on grade					
В	Shell							
B10	Superstructure							
B1010	Floor Construction							
B1012	Floor Decks, Slabs, & Toppings		6" concrete slab on grade					
B1020	Roof Construction							
B1021	Roof Structural Frame		Steel moment frame at App Bay as part of retrofit					
B1022	Roof Decks, Slabs, & Sheathing		1x8 T&G spanning to purlins supported on built up wood trusses					
B1025	Roof Construction Supplementary Components (fascia and flashing)		Mtl. Flashing needed at roof valley intersections, see B3010 section for addtl. Info.					
B1080	Stairs and Ladders							
B1088	Ladders	Hose-drying tower	Ladder appears to be compliant					
B20	Exterior Vertical Enclosures							
B2010	Exterior Walls							
B2011	Exterior Wall Structure		Wood stud walls, cement plaster and some walls with added structural sheathing done as part of retrofit; exterior cement plaster does not have required code separation from grade					
B2012	Exterior Wall Veneer		Cement plaster, no separation from grade, needs patch and paint Crack repaired near back stair from restroom leak, still soft; repair of sink not confirmed					
B2016	Equipment Screens		CMU wall screen at diesel tank, needs paint; chain link fence cage at emergency generator, some organic growth on slats					
B2020	Exterior Windows							
B2021	Exterior Windows		Windows new in 2021					

B2021.01	Exterior Windows at Sleeping Rooms Emergency Exit	1 and Dorms	Window sill height 45" and 45 1/2" which is >44"; non conforming per exiting requirements		
		, ,			
B2050	Exterior Doors				1
B2051	Exterior Doors	Front door	Mtl. Door/frame w/ lever hardware		
B2052	Exterior Doors		Wd. Door/frame w/ lever hardware, needs paint, no landing		
B2053	Exterior Doors		Wd. panel door repaired w/ sealant, knob hardware, needs replacement		
B2054	Exterior Doors		Wd. Door/frame w/ knob, screen door broken handle		
B2057	Exterior Overhead Doors		Two roll-up overhead doors into app bay		
B2070	Exterior Louvers & Vents				T
B2071	Exterior Louvers & Vents		Soffit vents approx. 15-feet on center		T
B30	Exterior Horizontal Enclosures				
B3010	Roofing				+
B3011	Steep Slope Roofing		Main roof is 5:12 asphalt shingle good condition, some organic growth north side; Mtl. Flashing needed at valley intersections		
B3015	Low-Slope Roofing	Rear of bldg. south at each corner	Low slope roof is rolled asphalt, cracked and needs replacement		1
B3018	Insulation at Roof	App Bay and above clg. on north and south wings	No insulation at roof envelope observed		
B3020	Roof Appurtenances	g-			+
B3027	Gutters & Downspouts		Alum. gutters, downspouts in good condition, need to be cleaned out; downspout termination is blocked in some cases		
B3060	Horizontal Openings				
B3065	Vents & Hatches	Interior ceiling one in closet one in hall	Interior ceiling hatches need paint		
B3080	Overhead Exterior Enclosures		-		+
B3082	Exterior Soffits	All	Wood w/ peeling paint		\top
С	Interiors				+
C10	Interior Construction			†	+

C1020	Interior Windows				
C1021	Interior Windows		Non rated window between dining room		
		Dining 2	and App Bay 8 - non conforming		
C1030	Interior Doors		See Summary page for fire rating and		
			Accessibility page for comments		
C1031	Interior Doors	Door 14	Wood door is damaged at latch		
C1040	Interior Grilles & Gates				
C1070	Suspended Ceiling Construction				
C1072	Plaster & Gypsum Board Ceilings	Hall 10	Plaster is bubbled and cracked - repair		
C1090	Interior Specialties				
C1096	Toilet, Bath, & Laundry Accessories		See Accessibility page		
C1096.01	Toilet Partition condition	Toilet Rm 9	Very rusty toilet partitions		
C1097	Storage Specialties		Existing kitchen storage under counter is		
			open shelving, hard to keep		
		Kitchen 3	clean/sanitary without doors		
C20	Interior Finishes				
C2010	Wall Finishes				
C2011	Tile Wall Finish		Damaged wall tile, base and wall board		
		Toilet Rm 9	behind custodial sink		
C2015	Stone Facing		Paint is damaged, repainting required		
C2017	Wall Painting & Coating		Interiors have old damaged paint, should		
		All	be repainted (1)		
C2020	Interior Fabrications				
C2030	Flooring				
C2031	Tile Flooring	Toilet Rm 9	Tile is in good shape		
C2032	Masonry Flooring		Painted concrete floor paint is worn,		
		Laundry 6	needs repainting		
C2034	Resilient Flooring	Kitchen 3	Resilient tile flooring damaged - replace		
	Resilient Flooring	Hall 10	Resilient tile flooring damaged - replace		
C2040	Resilient Floor Base	Office 4	No floor base installed		
C2050	Ceiling Finishes				
C2051	Plaster & Gypsum Board Finish	Hall 10	Plaster is bubbled and cracked - repair		
C2057	Ceiling Painting & Coating		Interiors have old damaged paint, should		
		all	be repainted (1)		
C2059	Attic Space Condition (insulated envelope)	all	See roofing item above		
D	Services				
D20	Plumbing				
D2010	Domestic Water Distribution				
D2012	Domestic Water Heater and/or boilers		Manufactured in 2019. In good condition.		
D2014	Domestic Water Piping		Hot water piping is not insulated for large		
			sections.		

11/3/2021

D2016	Plumbing Fixtures		One compartment sink in Kitchen 3;	
			Older 1.6GPF water closets. Lavatories	
		Kitchen 3	have controls that requiring grasping and	
		and other	twisting, not ADA compliant.	
D2020	Sanitary Drainage			
D2023	Sanitary Sewer Piping		No see the form of the state of	
			No reports from staff that there are issues	
D2030	Building Support Plumbing Systems			
D2032	Stormwater Drainage Piping		Rain water leaders from roof to runoff	
D2033	Stormwater Drains		Steel trench drain at grade in front of OH door in good condition	
D30	Heating, Ventilation, & Air Conditioning (HVAC)			
D3010	Facility Fuel Systems			
D3011	Fuel Piping			
D3013	Fuel Pumps			
D3015	Fuel Storage Tanks		Diesel tank outer conc. shell has cracks, needs patch and paint	
D3020	Heating Systems			
D3021	Heat Generation		Central Furnace mounted high in app bay provides heating to both sides of the FH. One year old. Great condition	
D3023	Thermal Heat Storage			
D3025	Decentralized Heating Equipment		A few electric heaters were found throughout the property. Most were not plugged in.	
D3027	Heating System Supplementary Components		Unit heater is located in app bay	
D3029	Electric Heating System			
D3030	Cooling Systems			
D3031	Central Cooling		Outdoor 5-Ton Condensing unit connected to central furnace. One year old	
D3037	Decentralized Cooling		A few move n cools located throughout building. Does not appear that they are in use. Workout studio has a move n cool that is in use	
D3060	Ventilation			
D3061	Supply Air & Grilles		Located throughout FH. Typical 12"x6" residential type grilles	
D3062	Return Air & Grilles		Located throughout FH. Typical 12"x6" residential type grilles	
D3063	Exhaust Air & Grilles		Located in restrooms and kitchen	
D3064	Outside Air		Operable windows	
D40	Fire Protection			

D4010	Fire Suppression					
D4011	Fire Sprinklers		No fire sprinkler system			
D4030	Fire Suppression Specialties					
D4031	Fire Extinguisher Cabinets					
D4033	Fire Extinguishers					
D4035	Commercial Kitchen Fire Suppression Systems					
D50	Electrical					
D5010	Facility Power Generation					
D5011	Emergency Generator for Standby Power		Kohler emergency generator with transfer swith located inside fence enclosure			
D5012	Battery Equipment					
D5014	UPS System					
D5017	Transfer Switches					
D5020	Electrical Service & Distribution					
D5021	Electrical Service		150A 120/240 single phase service. Service installed in 1997. Good condition			
D5022	Electrical Panels		Two zinsco panels located in App Bay. Should be replaced and relocated to somwehere outside the app bay			
D5023	Power Distribution		Exposed conduit throughout app bay			
D5031	Branch Wiring System		Appears to be in good condition			
D5040	Lighting					
D5041	Lighting Controls		Light switches in Dorms 11, 12, 13 are controlled outside of the rooms in oddly configured circuiting; wall switches are used, no occupancy sensors			
D5042	Branch Wiring for Lighting		Within conduit and in fair condition			
G4051	Area Lighting	Rear parking lot	LED post-mounted exterior led floodlight			
D5046	Lighting Fixtures Interior (working condition y/n)	App Bay 8	(3) light fixtures are missing protective cage; Overall mixture of T8 4', 8', compact fluorescent, surface mounted fixtures throughout. Due for LED upgrade			
D5047	Illuminated Exit Signage	All	None provided			
D5048	Exit Emergency Lighting					
D60	Communications			 		
D6010	Data Communications					
D6011	Data Communications Network Equipment		In Fair condition. Located in Comm room that is connected to dining room.			
D6020	Voice Communications					
D6021	Voice Communications Switch & Routing Equip.		Located in closet through captain's quarters.			

11/3/2021

D6022	Voice Communications Terminal Equipment		Located in closet through captain's		
DOULL	Voice Communications Terminal Equipment		quarters.		
D70	Electronic Safety & Security				
D7010	Access Control & Intrusion Detection				
D7011	Access Control		Card reader at pedestrian door		
D7050	Detection & Alarm				
D7051	Fire Detection & Alarm		Local 120V devices in dorm rooms		
D7053	Line Voltage Smoke Alarm				
D7053	Outdoor Warning Siren	Pole- mounted rear parking lot	Operation not verified		
E	Equipment & Furnishings				
E10	Equipment				
E1030	Equipment				
E1033	Laundry & Dry Cleaning Equipment		Washer and dryer - residential grade		
E1037	Office Equipment		Not reviewed		
E1038	Foodservice Equipment		Not reviewed		
E1061	Residential Appliances		Dishwasher and refridgerators are residential grade		
E1067	Residential Ceiling Fans		Yes, provided in dorms		
E20	Furnishings				
E2010	Fixed Furnishings				
E2012	Window Treatments		Existing louvered shades		
E2013	Casework		At kitchen only		
G	Sitework				
G20	Site Improvements				
G2020	Parking Lots				
G2021	Parking Lot Pavement	Lot at west and south of building	Asphalt with many patches and cracks, needs replacement, no striping		
G2030	Pedestrian Plazas & Walkways				
G2033	Exterior Steps & Ramps	corner of App	Non-compliant handrails and guard, no landing at exterior door; no striping at treads; door does not appear to be in use		
G2034	Exterior Steps & Ramps	corner of App Bay	Non-compliant handrails and guard, no striping at treads, no landing at exterior door		
G2035	Exterior Steps & Ramps	building from	Non-compliant handrails and guard, no striping at treads, no landing at exterior door		
G2060	Site Development				

G2062	Site Furnishings		Shipping container onsite for storage;			
	_		small outbuilding used for fitness room;			
		main building	Mop and tool hangers on outbuilding			
		at rear lot	north side			
G2063	Exterior Signage		No accessible signage; wayfinding			
			signage including FS 25 and front door;			
			Safe Surrender			
G2063	1. 1496-140	Exterior north				
		side of				
		property	Good condition			
G2066	Retaining Walls					
		Around base	Small stone wall, gravel spilling onto			
		of diesel tank	sidewalk			
G2080	Landscaping					

SPACE	ITEM	OPERATIONAL REVIEW	MODIFICATION	PRIORITY	РНОТО
Public Space	Lobby	This station does not have a lobby space. The public is greeted at a apparatus bay door.	Add public lobby.	High	Door to Apparatus bay
	Space for Well Checks	There is not an appropriate space for well checks.	Add public lobby with space for well checks	Medium - Recommended if station is renovated	
	Accessible Public Restroom	No dedicated public restroom	There is an accessible restroom off of the apparatus bay that can meet the requirement for accessibility. However, there is no accessible route to the station. If that station is renovated, we recommend creating a dedicated accessible restroom as a part of a new lobby.	Required if renovated	Restroom entrance from Captain's Office

SPACE	ITEM	OPERATIONAL REVIEW	MODIFICATION	PRIORITY	РНОТО
Apparatus Bays		Fair Condition, newly replaced. However, door opening is too narrow for newer apparatus.	Remove center support and install door that extends across the full opening.	Required if renovated	View of doors from the apparatus bay
	Floor Drains in Bay	No	Continue to use drain pans.	N/A	
	Vehicle Tailpipe Extraction System	Non-Operational, Currently the Department uses WARDS No Smoke for exhaust control.	Remove obsolete system	Low	Tail-pipe System to be removed
	Hand washing/medical clean-up in bay	There is not a dedicate clean up sink.	Add medical clean up sink if renovated	Recommended if station is renovated	і ан-ріре буѕієті то ре геттоуед

SPACE	ITEM	OPERATIONAL REVIEW	MODIFICATION	PRIORITY	РНОТО
	Shore power and Compressed Air	Shore power at engine bay and portable compressed air systems are adequate.	N/A	N/A	
	Alerting System Status/Acoustics	New head end equipment has been provided.	Replace obsolete speaking system with upgraded speakers and notification devises.	Medium - Recommended if station is renovated	Alerting System
Apparatus Support	Dedicated Turn out Storage Room with two lockers for assigned fire fighter	Turnouts stored in bay	Add on to the fire station to provide this necessary dedicate storage.	High	Existing turn out storage

SPACE	ITEM	OPERATIONAL REVIEW	MODIFICATION	PRIORITY	РНОТО
	Extractor and Dryer for apparatus and hose	Station only has residential units	Expand station to add a room for dedicated turnout storage and washer extractor/equipment dryer.	High	Existing laundry room
	Extractor and Dryer for apparatus and nose	Medical supply storage location was not	extractor/equipment dryer.	nign	Existing faundry room
	Medical Supply Storage	identified	N/A		
	Workshop	Workshop area in apparatus bay	Shop work area used for multiple functions. Modification of the obsolete hose tower is recommended for a more efficient layout.		

SPACE	ITEM	OPERATIONAL REVIEW	MODIFICATION	PRIORITY	РНОТО
	Hose Storage and Drying Tower	No backup hose storage at this location	Re-purpose tower area for an expansion of the shop and added storage.	Medium - Recommended if station is renovated	Tower at floor level
	Dedicated janitors room	There is a janitors space in the fire fighter restroom.	This space is adequate for the use, however, if the station was renovated this would be moved to the laundry room and a second janitors space would be added for just the apparatus bay and support areas.	Medium - Recommended if	Janitor Room in restroom

SPACE	ITEM	OPERATIONAL REVIEW	MODIFICATION	PRIORITY	РНОТО
	Dedicated Fitness Room	A shed at the rear of the property has been converted to a fitness room.	The shed lacks sufficient space for required equipment and the construction is substandard. Recommend that a fitness space is added to the fire station if renovated.	Medium - Recommended if station is renovated	Fitness Equipment in Shed
Office Space		A former bunk room has been converted to an office for use by the station crew. It also provides space for a refrigerator and medical	A watch office is typically off of a secure lobby. We recommend adding a lobby and converting the Captains office/bedroom to a functional office area for all fire fighters to use.	Medium - Recommended if station is renovated	Office space with other storage

SPACE	ITEM	OPERATIONAL REVIEW	MODIFICATION	PRIORITY	РНОТО
	Dedicated Comm. Room with air-conditioning	Comm equipment is in a closet off the Captains room and is not conditioned.	Create dedicated Comm Room. with space for rack mounting of equipment and a dedicated conditioning system.	Medium - Recommended if station is renovated	Data closet off Captains Office/bedroom
	Public Meeting room	Not required at this location	N/A		
Kitchen	Casework Condition	Currently being refurbished by the Fire Fighters assigned to this station.	N/A		Kitchen
		Counters are not stainless but are new and			
		appropriate for the use.	N/A		
	Adequate shift storage and house storage	Adequate Storage for dry goods	N/A		

SPACE	ITEM	OPERATIONAL REVIEW	MODIFICATION	PRIORITY	РНОТО
	Three refrigerators	The kitchen has a single refrigerator and a second is located in the former bunk room.	Expand kitchen area to accommodate all food storage systems.		Refrigerator in kitchen
	Accessible work area and sink	No accessible work area or sinks	Address in Kitchen expansion	Required if renovated	
	Range Ventilation Status	Good Condition	N/A		
Dining Room	Sized to accommodate shift change meeting	The dining room is also the day room and provides space for a computer work station. It is adequately size for the intended use as a dining room only.	Recommend relocating the dayroom function out of the dining room through a station expansion.	Medium - Recommended if station is renovated	Dining Area

SPACE	ITEM	OPERATIONAL REVIEW	MODIFICATION	PRIORITY	РНОТО
Dayroom	Sized to accommodate on duty shift	There is not a dedicated dayroom in this station.	Recommend adding a day room.	Medium - Recommended if station is renovated	Recliners in Dining Room
Laundry room		A mechanical room was converted to a laundry room.	Renovate space to add casework for storage. Enclose water heater.	Medium - Address with Station	Extractor/Washer/Dry and TO drying racks
	mop sink for house	Located in bathroom	Add mop sink to laundry room.		
	adequate storage	No	Replace lockers with casework and folding counters/supply storage shelving.		

SPACE	ITEM	OPERATIONAL REVIEW	MODIFICATION	PRIORITY	РНОТО
Sleeping	Privatized Living Quarters	The station has been renovated to provide private sleeping quarters.	The size of the rooms are generous.	N/A	Typical Sleeping Room open to hallway
	Emergency egress from sleeping room windows	The windows in the sleeping rooms appear to provide egress	N/A	N/A	Sleeping Room with egress windows

SPACE	ITEM	OPERATIONAL REVIEW	MODIFICATION	PRIORITY	РНОТО
Dressing	Locker placement to accommodate dynamic staffing models	The living quarters wing of the facility has been modified to provide private sleeping rooms and a gender neutral personnel locker area.	N/A		Personnel Lockers
	Gender neutral Restrooms with showers	Accommodations have been made for a gender neutral shower and dressing area. It was design as an accessible space when	Relocate if the station is renovated to be grouped with the other all gender restrooms. Reduce in size and relocate lockers.	Medium - Address with Station Renovation	Private Restroom

SPACE	ITEM	OPERATIONAL REVIEW	MODIFICATION	PRIORITY	РНОТО
Restrooms/Sh owers	Adequate number of restrooms for staffing (.75 per staff Member)	The number of fixtures exceeds the number normally associated with this level of staffing. There is a group bathroom.	Renovate restroom space to provide private all gender facilities.	Medium - Address with Station Renovation	Partial restroom view. Shower behind view.
	Accessible Staff Shower and restroom	An accessible, all gender restroom have been added to the station.	N/A		Firefighter restroom

SPACE	ITEM	OPERATIONAL REVIEW	MODIFICATION	PRIORITY	РНОТО
General Storage	Storage for Special Duty operations (USAR, ETC.)	Not required at this location.	N/A		
				Medium - Address with Station	
Site Security	Site perimeter secured.	The site is not secured.	Fence site.	Renovation	View of rear yard property line.
Fire Alert	Fire Station Dispatch Alert System Status	New System at this location	N/A		
	Gas Shut off at Stove	Yes			
	Gas shut off at BBQ	No			
		All surfaces are worn and are recommended	Replace paying if facility is	Medium - Address with Station	
Site	Exterior paved surfaces: aprons, parking lot, driveway		renovated.		Front Apron

SPACE	ITEM	OPERATIONAL REVIEW	MODIFICATION	PRIORITY	РНОТО
	Operation of fuel pumps , fuel pump hoses, and nozzles	Fueling systems are operational	Would recommend relocating these systems to the rear of the station site.		Existing fueling system with generator behind.
	Inspection of above ground tanks by Environmental Services	Unknown	N/A		
	Adequate parking for shift change	S S	N/A		
		Would be included in a paving replacement	Add to paving scope of work if facility is renovated.		